






















Great Western Road, Glasgow.






















The Garden City: Letchworth, a panorama taken in 1912. The town was begun in 1903 with low densities, a rational organisation






FIG. 52.—HINDRANCES TO STREET TREES.

(A section of Kingsway, London.)

Subway for trams.

B B Sewers.

C C Gas mains.

11D Water mains.

E E Electric cables.

F Telephone conduit.

Telegraph conduit. . G

HH Surface water drains.

II Cellars.

J J Asphalt path. K K Buildings.

L Wood paving.

M Concrete.

N N Gulleys.

